



A

B

C

D



型式_Model	A
PL-HLDL3-150-HO	154
PL-HLDL3-300-HO	304
PL-HLDL3-450-HO	454
PL-HLDL3-600-HO	604

本製品は偏光フィルムと保護板の間に気泡が発生する可能性があります。
 _This product there is a possibility you to bubble protection plates and the polarizing film that occurs.

UNIT:mm

REVISION	DATE	DESCRIPTION	REVISED
000			

ISSUE DATE	SCALE	APPROVED	NAME
2021/08/04	1:2	T.OSAWA	PL-HLDL3-600-HO
	SHEET SIZE	CHECKED	DRAWING NAME
	A4	Y.INOUE	外観図_Outline
	PROJECTION	DESIGNED	DRAWING No.
		H.TOYOTA	REVISION SHEET
		DRAWN	000 01/01
		H.TOYOTA	UA39431-G