



PL-LDL2-74X30-WGFHO



- ※Accessories
- M3 Trass screw 5 pcs.
 - M3 Nut 5 pcs.

<Notes>

There is the possibility that air bubbles are generated between polarizing film and protection plate.