



A

B

C

D



型式_Model	A	B
PL-HLDL3-1050-VE	1054	(527)
PL-HLDL3-1200-VE	1204	(602)
PL-HLDL3-1350-VE	1354	(677)
PL-HLDL3-1500-VE	1504	(752)
PL-HLDL3-1650-VE	1654	(827)
PL-HLDL3-1800-VE	1804	(902)

本製品は偏光フィルムと保護板の間に気泡が発生する可能性があります。  
 This product there is a possibility you to bubble protection plates and the polarizing film that occurs.  
 偏光フィルムは照明の中央部に継ぎ目が有ります。  
 Polarizing film has a seam at the central portion of lighting.

UNIT:mm

REVISION	DATE	DESCRIPTION	REVISED
000			

ISSUE DATE	SCALE	APPROVED	NAME
2021/10/29	1:2	T.OSAWA	PL-HLDL3-1800-VE
	SHEET SIZE	CHECKED	DRAWING NAME
		DESIGNED	外観図_Outline
		DRAWN	DRAWING No.
		DRAWN	REVISION SHEET
		H.TOYOTA	UA37517-G
		H.TOYOTA	000 / 01